

B31/RB1

There have been a few pedals that are falling off this dual action bike. A large percentage of them are falling off the right side. In the past we have placed lock tight on the threads and tightened it. This only works a small percentage of the time.

The link arm bushing and pedals are a tight fit. Because of the tight fit and lack of lubrication on that pivot point it seizes up and unscrews the pedal arm. If lithium grease is placed on that joint it will slide w/little resistance and work properly.

The best way to take care of the problem is to thread lock the threads, put lithium grease on the bushing pedal point and tighten. Out of the units we have tested here this seems to be the best fix.